



Port Of Prescott



A Division of the Township of Edwardsburgh/Cardinal

The Port of Prescott will be performing repairs to their ship loading spouts. The repairs consist mainly in the replacement of the telescoping spouts and miscellaneous repairs to the loading spout booms.

A mandatory site visit to review the work and distribute tender documents will be held on July 20th, 2011, 10 am at the Port.

All parties interested in bidding on this work and attending the above site meeting or making enquiries must contact

Robert Dalley

General Manager

Port of Prescott

3035 County Rd #2

Prescott, Ont

K0E 1T0

Tel. 613.925.4228 X101

Fax 613.925.5022

E-Mail: dalleyr@portofprescott.com

The Port of Prescott makes no commitment to proceed with project or to accept lowest bid of any tender.